

Gleitwax / Glidewax



Base Cleaning

S3 Yellow

Vor dem Waxen, Skibelag mit Waxentferner reinigen. Skilauffläche gut auslüften lassen. Oder mit Toko System-3 yellow heiss auswaxen. (einwaxen, abziehen, mit Kupferbürste ausbürsten)

Before waxing, clean the base with Toko waxremover. Leave the base to dry very well. Or hotclean with Toko System-3 yellow. (waxing, scraping, brushing)

Basispräparation / Basepreparation

LF Blue

Nach ca. 1 Stunde Abkühlung den Ski mit der Toko Plexiklinge abziehen und mit der Toko Nylon- oder Kupferbürste gut ausbürsten.

After about 1 hour cooling down, scrape the ski with the Toko Plexiblade and brush with Toko Nylon- or Copper brush.

Rennpräparation / Racepreparation

HF White

Nach ca. 1 Stunde Abkühlung den Ski mit der Toko Plexiklinge abziehen und mit der Toko Nylon- oder Kupferbürste gut ausbürsten.

After about 1 hour cooling down, scrape the ski with the Toko Plexiblade and brush with Toko Nylon- or Copper brush.

Finish / Topfinish (100% Fluoro Pulver / Powder)

Jetstream Red Powder

Einbügeln, gut auskühlen lassen, danach gut ausbürsten

Ironing, cooling-down well, brushing very well.

Finish / Topfinish (100% Fluoro Bloc / Bloc)

Jetstream Red Bloc

2-3 Schichten Bloc auftragen, jede Schicht gut verkorken.

Apply 2-3 layers of bloc. Cork each layer very well.

Bemerkungen / Notes

